


# CORNER RECORD

Agency Index BK 23, PG 39  
Document Number 20200083

City of Rocklin County of Placer, California  
Brief Legal Description Centerline intersection Mountain View Dr. & Antelope Way, Bk. L of Maps, Pg. 86

<p>Se 18</p> 	<p><b>CORNER TYPE</b></p> <p><input type="checkbox"/> Government Corner <input checked="" type="checkbox"/> Control</p> <p><input type="checkbox"/> Meander <input type="checkbox"/> Property</p> <p><input type="checkbox"/> Rancho <input type="checkbox"/> Other</p> <p>Date of Survey <u>October 16, 2020</u></p>	<p><b>COORDINATES (Optional)</b></p> <p>N. _____ E. _____</p> <p>Elevation _____</p> <p>Units <input type="checkbox"/> Metric <input type="checkbox"/> U.S. Survey Foot</p> <p>Horizontal Datum _____</p> <p>Zone _____ Epoch Date _____</p> <p>Vertical Datum _____</p> <p><input type="checkbox"/> Complies with Public Resources Code §§8801-8819</p> <p><input type="checkbox"/> Complies with Public Resources Code §§8890-8902</p>
--	---	--

T. 11 N., R. 7 E., M.D.B. & M.

PLS Act Ref.:	<input type="checkbox"/> 8765(d)	<input checked="" type="checkbox"/> 8771	<input type="checkbox"/> 8773	<input type="checkbox"/> Other:
Corner/Monument:	<input checked="" type="checkbox"/> Left as found	<input type="checkbox"/> Established	<input type="checkbox"/> Rebuilt	<input checked="" type="checkbox"/> Pre-Construction
	<input type="checkbox"/> Found and tagged	<input type="checkbox"/> Reestablished	<input checked="" type="checkbox"/> Referenced	<input type="checkbox"/> Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

Found railroad spike with punch at the centerline intersection of Mountain View Drive and Antelope Way, as shown on Antelope Oaks Unit No. 1, Bk. L of Maps, Pg. 86 that could be damaged or destroyed by a proposed paving project. Monument was referenced as shown on page 2 of 2. The purpose of this Corner Record is to preserve the location of the monument prior to construction. No attempt was made to determine the relationship between the monument and boundary lines.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on January 14, 2021

Signed [Signature] P.L.S. or R.C.E. No. P.L.S. 5914



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 26, 2021

and examined and filed JANUARY 29, 2021

Signed [Signature] P.L.S. or R.C.E. No. 8373

Title Deputy Co. Surveyor

County Surveyor's Comment



BOOK 23 OF CORNER RECORDS, PAGE 39



SCALE: 1"= 40'

